

IP-Symcon Verwaltungskonsole

Ansicht hinzufügen Aktualisieren Hilfe Über...

Meldungen ? ? X

Filter Schnellfilter AutoScroll Datensätze limitieren 100 Leeren

Datum/Zeit	Versender	Nachricht
12.01.2012 21:16:29	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 4,6
12.01.2012 21:16:29	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit Durchschnitt] = 4,5
12.01.2012 21:16:29	TimerID #8, TimerThread #2	[7 - Solar Vorlauf] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:16:30	TimerID #3, TimerThread #9	[2 - Pufferspeicher Oben] = 1-Wire Setup failed: 3
12.01.2012 21:16:31	TimerID #10, TimerThread #8	[Aussen] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:16:33	TimerID #4, TimerThread #3	[5 - Heizung Vorlauf] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:16:34	TimerID #5, TimerThread #5	[6 - Heizung Rücklauf] = 1-Wire Setup failed: 3
12.01.2012 21:16:35	TimerID #9, TimerThread #10	[1 - Holzvergaser] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:16:36	TimerID #6, TimerThread #9	[9 - Ölkessel] = 1-Wire Setup failed: 3
12.01.2012 21:16:49	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 4,4
12.01.2012 21:16:59	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 4,6
12.01.2012 21:17:09	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 5,9
12.01.2012 21:17:16	TimerID #14, TimerThread #7	[DS2450] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:17:17	TimerID #7, TimerThread #9	[8 - Solar Rücklauf] = 1-Wire Setup failed: 3
12.01.2012 21:17:19	TimerID #2, TimerThread #9	[3 - Pufferspeicher Mitte] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:17:29	VariableManager	[WMRS200 Windsensor\Windrichtung] = 247,5
12.01.2012 21:17:29	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 3,5
12.01.2012 21:17:30	TimerID #8, TimerThread #10	[7 - Solar Vorlauf] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:17:31	TimerID #3, TimerThread #9	[2 - Pufferspeicher Oben] = 1-Wire Setup failed: 3
12.01.2012 21:17:32	TimerID #10, TimerThread #6	[Aussen] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:17:34	TimerID #4, TimerThread #10	[5 - Heizung Vorlauf] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:17:35	TimerID #5, TimerThread #7	[6 - Heizung Rücklauf] = 1-Wire Setup failed: 3
12.01.2012 21:17:35	TimerID #9, TimerThread #8	[1 - Holzvergaser] = Could not start 1-Wire speed, Result: -12
12.01.2012 21:17:36	TimerID #6, TimerThread #10	[9 - Ölkessel] = 1-Wire Setup failed: 3
12.01.2012 21:17:39	VariableManager	[WMRS200 Windsensor\Windrichtung] = 292,5
12.01.2012 21:17:39	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 4,4
12.01.2012 21:17:59	VariableManager	[WMRS200 Windsensor\Windgeschwindigkeit] = 3,8

Willkommen Meldungen Objektbaum